



NEWS

GF Piping Systems

2882 Dow Avenue, Tustin, CA 92780-7258 • Tel. (714) 731-8800 / (800) 854-4090, Fax (714) 731-6201
e-mail: us.ps@georgfischer.com • www.gfpiping.com

To: GF Piping Systems Distributors

Date: November 14, 2010

**From: Dave Vollaire
Product Manager**

Issue: 33/10

Recall and Warning Notice

Effective immediately, GF Piping Systems is issuing a voluntary recall of all Signet integral PVDF paddlewheels due to potential leakage. This notice affects all PVDF integral paddlewheel sensors with a manufacturing date prior to September 1, 2010. Current and future orders will be fulfilled with product manufactured after this date. We request that all GF distributors involved in sales of Signet Instrumentation act in accordance with this recall and notify customers who have purchased product with integral mount sensors. **Failure to follow this request may result in injury to persons and/or damage to property.**

3-2537 Series

For field and inventory replacements, we recommend the affected 2537s be replaced with new units provided by the factory.

Mfr. Part No.	Code
3-2537-1C-T0	159 001 315
3-2537-2C-T0	159 001 316
3-2537-3C-T0*	159 001 317
3-2537-4C-T0*	159 001 318
3-2537-5C-T0	159 001 319
3-2537-6C-T0	159 001 320

* If purchased prior to July 16, 2010, 3-2537-3C-T0 will be replaced by 3-2537-1C-T0.

3-2537-4C-T0 will be replaced by 3-2537-2C-T0.

All Other PVDF Integral Sensors

For field and inventory replacements, we recommend the affected PVDF integral paddlewheel sensors be replaced with new PVDF sensors (8510s and 8512s) provided by the factory.

PVDF Body Flow Integral Systems

Mfr. Part No./Code	Description
198 864 804	Integral 3-8550-1 w/ 3-8510-T0
198 864 803	Integral 3-8550-1 w/ 3-8510-V0
198 864 834	Integral 3-8550-1 w/ 3-8512-T0
198 864 833	Integral 3-8550-1 w/ 3-8512-V0
198 864 814	Integral 3-8550-2 w/ 3-8510-T0
198 864 813	Integral 3-8550-2 w/ 3-8510-V0
198 864 844	Integral 3-8550-2 w/ 3-8512-T0
198 864 843	Integral 3-8550-2 w/ 3-8512-V0

Mfr. Part No.	Code
3-8150-T0	159 001 011
3-8150-V0	159 001 012
3-8510-T0	159 000 622
3-8510-V0	198 864 506
3-8512-T0	198 864 518
3-8512-V0	198 864 516

Please contact Customer Service to enter a no-charge PO number for replacement parts. We expect a returned sensor for every zero-charge unit we send out. Distributor will be charged if returned product is not received within 60 days. For new installations, purchases can be made same as normal.

We apologize for this inconvenience; however, we feel these measures are required to ensure safe and reliable use of Signet products. If you have further question, please contact me.